

# **EXHIBIT F**

PENGAD 800-631-6939

S Elliot

6-25-04

## JOB WORK ORDER

WO 5220

LABOR AND TRAVEL							
ODOMETER OUT		ODOMETER IN		ODOMETER RETURN			
TIME OUT	AM PM	TIME IN	AM PM	TECHNICIANS			
9:00	AM	9:15	PM	109			
TIME OUT	AM PM	TIME RETURN	AM PM	TRUCK NO.			
10:30	PM		PM	T-3			
JOB	HOURS	RATE	TOTAL	JOB TOTAL			
JOB OT							
TRAVEL				TRAVEL TOTAL			
TRAVEL OT							
MILES	OUT	RETURN	TOTAL	RATE	MILES TOTAL		
TOTAL							

Put new batteries  
in panel, dialer and  
radio tested all  
equip codes all  
works ok. I would  
send her some info  
on up grades

1.50

SIGNATURE I hereby acknowledge satisfactory completion of the above described work.

PRINT

DATE \_\_\_\_\_